Sri, B.K.R GEO CONSULTANTS

No 41, Srigandha Kaval, D. Group Layout, Nagarbhavi 2nd Stage,
Bangalore-560072 Ph:- 9113926141

DATE: 06.01.2022

REPORT ON GROUND WATER INVESTIGATION

01. Name of the Party	**Asst Executive Engineer, BBMP, Yeshwantpur Sub-Division.**
02. Location of land/Site	B.K Nagar, 11th Cross, Ward no 37, Yeshwantpur.
03. Purpose of Ground Water	Drinking water
04. Area	Yeshwantpur.
05. Approximate Drilling Depth	400-410 rmt
06. Approximate Casing Pipe	40-50 rmt
07. PVC Pipe	10-15 rmt
08. Expected Yield	1500-2000 GPH
09. Remarks	-

Note: Although the best site for drilling has been suggested. NO GUARANTEE of success can be given and we will not be liable in any way for any loss to the party in respect of the well drilled at the recommended being failure

B.K.R Geo Consultants

Proprietor

Scanned with CamScanner

Sri, B.K.R GEO CONSULTANTS

No 41, Srigandha Kaval, D. Group Layout, Nagarbhavi 2nd Stage,
Bangalore-560072 Ph:- 9113926141

DATE: 06.01.2022

REPORT ON GROUND WATER INVESTIGATION

01. Name of the Party	**Asst, Executive Engineer, BBMP, Yeshwantpur Sub-Division.**
02. Location of land/Site	Rammandir, Ward no 37, Yeshwantpur.,
03. Purpose of Ground Water	Drinking water
04. Area	Yeshwantpur.
05. Approximate Drilling Depth	420-430 rmt
06. Approximate Casing Pipe	40-50 rmt
07. PVC Pipe	10-15 rmt
08. Expected Yield	1500-2000 GPH
09 Remarks	

Note: Although the best site for drilling has been suggested. NO GUARANTEE of success can be given and we will not be liable in any way for any loss to the party in respect of the well drilled at the recommended being failure

B.K.R Geo Consultants

Proprietor

Scanned with CamScanner

Sri, B.K.R GEO CONSULTANTS

No 41, Srigandha Kaval, D. Group Layout, Nagarbhavi 2nd Stage,
Bangalore-560072 Ph:- 9113926141

DATE: 07.01.2022

REPORT ON GROUND WATER INVESTIGATION

01. Name of the Party	**Asst, Executive Engineer, BBMP, Yeshwantpur Sub-Division.**
02. Location of land/Site	NTR Front Road, Ward no 37, Yeshwantpur.
03. Purpose of Ground Water	Drinking water
04. Area	Yeshwantpur.
05. Approximate Drilling Depth	410-420 rmt
06. Approximate Casing Pipe	40-50 rmt
07. PVC Pipe	10-15 rmt
08. Expected Yield	1500-2000 GPH
09 Remarks	

Note: Although the best site for drilling has been suggested. NO GUARANTEE of success can be given and we will not be liable in any way for any loss to the party in respect of the well drilled at the recommended being failure

B.K.R Geo Consultants

Proprietor

Scanned with CamScanner

Sri, B.K.R GEO CONSULTANTS

No 41, Srigandha Kaval, D. Group Layout, Nagarbhavi 2nd Stage,
Bangalore-560072 Ph:- 9113926141

DATE: 08.01.2022

REPORT ON GROUND WATER INVESTIGATION

01. Name of the Party	**Asst, Executive Engineer, BBMP, Yeshwantpur Sub-Division.**
02. Location of land/Site	S.K Jewellary Road, Ward no 37, Yeshwantpur.
03. Purpose of Ground Water	Drinking water
04. Area	Yeshwantpur.
05. Approximate Drilling Depth	400-420 rmt
06. Approximate Casing Pipe	40-50 rmt
07. PVC Pipe	10-15 rmt
08. Expected Yield	1500-2000 GPH
09 Remarks	

Note: Although the best site for drilling has been suggested. NO GUARANTEE of success can be given and we will not be liable in any way for any loss to the party in respect of the well drilled at the recommended being failure

B.K.R Geo Consultants

Proprietor

Scanned with CamScanner

Sri, B.K.R GEO CONSULTANTS

No 41, Srigandha Kaval, D. Group Layout, Nagarbhavi 2nd Stage,
Bangalore-560072 Ph:- 9113926141

DATE: 08.01.2022

REPORT ON GROUND WATER INVESTIGATION

01. Name of the Party	**Asst, Executive Engineer, BBMP, Yeshwantpur Sub-Division.**
02. Location of land/Site	Shalya Beauty parlour, Ward no 37, Yeshwantpur.
03. Purpose of Ground Water	Drinking water
04. Area	Yeshwantpur.
05. Approximate Drilling Depth	410-430 rmt
06. Approximate Casing Pipe	40-50 rmt
07. PVC Pipe	10-15 rmt
08. Expected Yield	1500-2000 GPH
09 Remarks	

Note: Although the best site for drilling has been suggested. NO GUARANTEE of success can be given and we will not be liable in any way for any loss to the party in respect of the well drilled at the recommended being failure

B.K.R Geo Consultants

Proprietor

Scanned with CamScanner

Sri, B.K.R GEO CONSULTANTS

No 41, Srigandha Kaval, D. Group Layout, Nagarbhavi 2nd Stage,
Bangalore-560072 Ph:- 9113926141

REPORT ON GROUND WATER INVESTIGATION

DATE: 09.01.2022

01. Name of the Party	**Asst, Executive Engineer, BBMP, Yeshwantpur Sub-Division.**
02. Location of land/Site	Ward office road, Ward no 37, Yeshwantpur.
03. Purpose of Ground Water	Drinking water
04. Area	Yeshwantpur.
05. Approximate Drilling Depth	400-410 rmt
06. Approximate Casing Pipe	40-50 rmt
07. PVC Pipe	10-15 rmt
08. Expected Yield	1500-2000 GPH
09 Remarks	

Note: Although the best site for drilling has been suggested. NO GUARANTEE of success can be given and we will not be liable in any way for any loss to the party in respect of the well drilled at the recommended being failure

B.K.R Geo Consultants

Proprietor

Scanned with CamScanner

Sri, B.K.R GEO CONSULTANTS

No 41, Srigandha Kaval, D. Group Layout, Nagarbhavi 2nd Stage,
Bangalore-560072 Ph:- 9113926141

REPORT ON GROUND WATER INVESTIGATION

DATE: 09.01.2022

01. Name of the Party	**Asst, Executive Engineer, BBMP, Yeshwantpur Sub-Division.**
02. Location of land/Site	JDS Office road, Ward no 37, Yeshwantpur.
03. Purpose of Ground Water	Drinking water
04. Area	Yeshwantpur.
05. Approximate Drilling Depth	410-420 rmt
06. Approximate Casing Pipe	40-50 rmt
07. PVC Pipe	10-15 rmt
08. Expected Yield	1500-2000 GPH
09 Remarks	

Note: Although the best site for drilling has been suggested. NO GUARANTEE of success can be given and we will not be liable in any way for any loss to the party in respect of the well drilled at the recommended being failure

B.K.R Geo Consultants

Proprietor

Scanned with CamScanner

Sri, B.K.R GEO CONSULTANTS

No 41, Srigandha Kaval, D. Group Layout, Nagarbhavi 2nd Stage,
Bangalore-560072 Ph:- 9113926141

REPORT ON GROUND WATER INVESTIGATION

DATE: 10.01.2022

01. Name of the Party	**Asst, Executive Engineer, BBMP, Yeshwantpur Sub-Division.**
02. Location of land/Site	B.K Nagar, 2nd main road, Ward no 37, Yeshwantpur.
03. Purpose of Ground Water	Drinking water
04. Area	Yeshwantpur.
05. Approximate Drilling Depth	400-420 rmt
06. Approximate Casing Pipe	40-50 rmt
07. PVC Pipe	10-15 rmt
08. Expected Yield	1500-2000 GPH
09 Remarks	

Note: Although the best site for drilling has been suggested. NO GUARANTEE of success can be given and we will not be liable in any way for any loss to the party in respect of the well drilled at the recommended being failure

B.K.R Geo Consultants

Proprietor

Scanned with CamScanner

Sri, B.K.R GEO CONSULTANTS

No 41, Srigandha Kaval, D. Group Layout, Nagarbhavi 2nd Stage,
Bangalore-560072 Ph:- 9113926141

REPORT ON GROUND WATER INVESTIGATION

DATE: 11.01.2022

01. Name of the Party	Asst, Executive Engineer, BBMP, Yeshwantpur Sub-Division.
02. Location of land/Site	B.K Nagar, Vinayaka Temple, Ward no 37, Yeshwantpur.
03. Purpose of Ground Water	Drinking water
04. Area	Yeshwantpur.
05. Approximate Drilling Depth	420-430 rmt
06. Approximate Casing Pipe	40-50 rmt
07. PVC Pipe	10-15 rmt
08. Expected Yield	1500-2000 GPH
09 Remarks	

Note: Although the best site for drilling has been suggested. NO GUARANTEE of success can be given and we will not be liable in any way for any loss to the party in respect of the well drilled at the recommended being failure

B.K.R Geo Consultants

Proprietor

Scanned with CamScanner

Sri, B.K.R GEO CONSULTANTS

No 41, Srigandha Kaval, D. Group Layout, Nagarbhavi 2nd Stage,
Bangalore-560072 Ph:- 9113926141

REPORT ON GROUND WATER INVESTIGATION

DATE: 12.01.2022

01. Name of the Party	**Asst, Executive Engineer, BBMP, Yeshwantpur Sub-Division.**
02. Location of land/Site	B.K Nagar, 13th Cross, Ward no 37, Yeshwantpur.
03. Purpose of Ground Water	Drinking water
04. Area	Yeshwantpur.
05. Approximate Drilling Depth	390-410 rmt
06. Approximate Casing Pipe	40-50 rmt
07. PVC Pipe	10-15 rmt
08. Expected Yield	1500-2000 GPH
09 Remarks	

Note: Although the best site for drilling has been suggested. NO GUARANTEE of success can be given and we will not be liable in any way for any loss to the party in respect of the well drilled at the recommended being failure

B.K.R Geo Consultants

Proprietor

Scanned with CamScanner

Sri, B.K.R GEO CONSULTANTS

No 41, Srigandha Kaval, D. Group Layout, Nagarbhavi 2nd Stage,
Bangalore-560072 Ph:- 9113926141

REPORT ON GROUND WATER INVESTIGATION

DATE: 12.01.2022

01. Name of the Party	Asst, Executive Engineer, BBMP, Yeshwantpur Sub-Division.
02. Location of land/Site	Ajana Network opp road, Ward no 37, Yeshwantpur.
03. Purpose of Ground Water	Drinking water
04. Area	Yeshwantpur.
05. Approximate Drilling Depth	410-420 rmt
06. Approximate Casing Pipe	40-50 rmt
07. PVC Pipe	10-15 rmt
08. Expected Yield	1500-2000 GPH
09 Remarks	

Note: Although the best site for drilling has been suggested. NO GUARANTEE of success can be given and we will not be liable in any way for any loss to the party in respect of the well drilled at the recommended being failure

B.K.R Geo Consultants

Proprietor

Scanned with CamScanner